7 MINUTE HAT

Bulky machine 3 Ozs, worsted weight yarn Tension 7 and 8

- 1. Bring out EON, L37-R36, tension 7
- 2. Knit one row from right to left
- 3. Hang cast on comb with the teeth coming toward you on the yarn between the needles
- 4. Bring the out of work needles into work
- 5. Knit 40 rows
- 6. Bring EON to hold, holding onto to comb making sure you keep some tension on the comb so you don't lose the stitches off the comb, with a weighted bar across the knitting fold in half and hang the cast on loops on the needles in hold. You just hung the hem for the hat
- 7. Change to tension 8
- 8. Knit 20 rows
- 9. Transfer EON, PUT EMPTY NEEDLES OUT OF WORK
- 10. Knit 4 rows
- 11. Sew off with a double eyed needle
- 12. Gather up top of hat and sew up the seam

Instructor, Karalyn Rainey 7/12/2021

